

# **EASTERN BUILDING INSPECTION SERVICES**

- **Property Location:**
- **8 Douglas Street**
- **Sydney**
- **Nova Scotia**
  
- **Date:**  
**March 3/2007**

.....

# Eastern Building Inspection Services

ROOF - 20+ years

ESTIMATED REPLACEMENT 0 to 2 years

ELECTRICAL- SERVICE AMPS - 100 amp copper, fuse type,  
copper wire

OIL TANK- AGE - UNKNOWN, 200 gallon

NON-COMBUSTIBLE BASE YES

VENT PIPE EXCEEDS HEIGHT OF FILL PIPE NO

OIL LINE LOOPED AND ENCAPSULATED NO



LOCATION EXTERIOR

AGE OF FURANCES - 10+ years

TYPE OF PLUMBING WASTE LINES-

Sewer lines- Black iron and ABS

Potable water lines- copper



.....